



Resistivitetslog
Fluid-resistivitet



Naturlig gammalog
Temperaturlog



Borehulslogging

Rekvirent:
Dall Villaby Vandværk
Hyrindevej 12
9230 Svenstrup

Titel:
Dall Villaby
- DGU nr. 34.3208
Dybdeinterval 0 - 70 m.u.t.

Kurveinformation - venstre

- 8" normallog
- 16" normallog
- 32" normallog
- 64" normallog
- Fluid-resistivitet

Kurveinformation - Højre

- Temperaturlog
- Naturlig gammalog
- Gammalog - filtersat

Data og optageinformationer

DybderefERENCE niveau : Terræn
Optagelser udført : 20.11.2007 + 20.12.2007/ALP
Sti: \\2007\13107008\Data\..\dall_villaby.grf

Resistivitetslog:

Hast. : 3 m/min (op), Datafil : ea3.las
Sampling: 2,5 cm, Filter : Ingen

Temperaturlog:

Hast. : 8 m/min (ned), Datafil : wa1.las
Sampling: 2,5 cm, Filter : Ingen

Naturlig gammalog:

Hast. : 3 m/min (op), Datafil : ga2.las+ea3.las
Sampling: 1 cm, Filter : non-spike mean 25 cm

Bemærkninger:



| | |
|---------------------|----------------------|
| Sagsnr: 13107008 | Dato: 21.12..2007 |
| Udarbejdet: ALP | Kontrol: HAN |

Jens Juuls Vej 18
8260 Viby J
Telefon 87 38 16 66
Telefax 87 38 16 99